

Mercury/Mariner



18-5881 Switch Box
Replaces 332-5772A7

ORDER NO.	PRICE
SIE 185881	\$219.00




18-5776 Switch Box
Replaces: 339-7452A3

ORDER NO.	PRICE
SIE 185776	\$124.00



18-5777 Switch Box
Replaces: 339-7452A15

ORDER NO.	PRICE
SIE 185777	\$144.00



18-5778 Switch Box
Replaces: 339-7452A14

ORDER NO.	PRICE
SIE 185778	\$159.00



Service Coils



OMC
Replaces: 582995

ORDER NO.	PRICE
SIE 185181	\$28.99



OMC
Replaces: 581786

ORDER NO.	PRICE
SIE 185172	\$41.49



OMC
Replaces: 581407

ORDER NO.	PRICE
SIE 185196	\$35.49



ORDER NO.	DESCRIPTION	PRICE
SIE 185192	Replaces: 582091	\$34.99



Plug-In Coil

Replaces: 582508
OMC

ORDER NO.	PRICE
SIE 185179	\$24.99



Mercury
Replaces: 339-7370A13

ORDER NO.	PRICE
SIE 185186	\$29.99



18-5775 Switch Box

Replaces: 332-7778A6,
332-7778A9

ORDER NO.	PRICE
SIE 185775	\$164.00



OMC

Replaces: 582366,
583737, 584561

ORDER NO.	PRICE
SIE 185176	\$24.99



Switch Box
Replaces: Mercury 339-7452A19 Fits:
2 cyl. w/Ring Terminals

ORDER NO.	PRICE
MAL 925102	\$136.91