

Mercury/Mariner



18-5881 Switch Box
Replaces 332-5772A7

ORDER NO.	PRICE
SIE 185881	\$219.00




18-5776 Switch Box
Replaces: 339-7452A3

ORDER NO.	PRICE
SIE 185776	\$119.00



18-5777 Switch Box
Replaces: 339-7452A15

ORDER NO.	PRICE
SIE 185777	\$144.00



18-5778 Switch Box
Replaces: 339-7452A14

ORDER NO.	PRICE
SIE 185778	\$154.00



Service Coils



OMC
Replaces: 582995

ORDER NO.	PRICE
SIE 185181	\$22.49



OMC
Replaces: 581786

ORDER NO.	PRICE
SIE 185172	\$38.49



OMC
Replaces: 581407

ORDER NO.	PRICE
SIE 185196	\$32.99



ORDER NO.	DESCRIPTION	PRICE
SIE 185192	Replaces: 582091	\$34.99



Mercury
Replaces: 339-7370A13

ORDER NO.	PRICE
SIE 185186	\$29.99




Plug-In Coil
Replaces: 582508
OMC

ORDER NO.	PRICE
SIE 185179	\$23.49



OMC
Replaces: 582366,
583737, 584561

ORDER NO.	PRICE
SIE 185176	\$23.49



18-5775 Switch Box
Replaces: 332-7778A6,
332-7778A9

ORDER NO.	PRICE
SIE 185775	\$164.00