



**OMC  
18-2132  
Trim Hose**  
(Manifold to Cylinder), (Starboard Down)  
Replaces: 983946, 985614.

ORDER NO.	PRICE
SIE 182132	\$44.99



**OMC  
18-2133  
Trim Hose**  
(Manifold to Cylinder), (Starboard Up)  
Replaces: 983947, 985615.

ORDER NO.	PRICE
SIE 182133	\$44.99



**OMC  
18-2134  
Trim Hose**  
(Manifold to Cylinder)  
(Port Down)  
Replaces: 983948, 985616

ORDER NO.	PRICE
SIE 182134	\$45.49



**Volvo  
18-2122  
Power Trim Hose**  
Replaces: 850906-9

ORDER NO.	PRICE
SIE 182122	\$86.49

**Volvo Penta  
18-2121  
Power Trim Hose**  
Replaces: 850907-7



ORDER NO.	PRICE
SIE 182121	\$82.99



**18-2135  
Trim Hose**  
(Manifold to Cylinder) (Port Up)  
Replaces: 984024, 985617

ORDER NO.	PRICE
SIE 182135	\$46.99

**OMC  
King Cobra  
18-2246  
Shift Cable Assembly**  
Replaces: 987678 OMC



ORDER NO.	PRICE
SIE 182246	\$164.00



**18-2158  
Shift Cable Assembly**  
Replaces: 73679A2, 73723A1  
Mercruiser 1 drives S/N 1562900-6225576.



ORDER NO.	PRICE
SIE 182158	\$66.99

**18-2157  
Shift Cable Assembly**  
Replaces: 41951A1  
Mercruiser 1 drives S/N 6225577 & UP.



ORDER NO.	PRICE
SIE 182157	\$68.49



**18-2159  
Inner Shift Cable**  
Replaces: 66069A2  
Use in 18-2157, 18-2158 and their Mercruiser equivalent as replacement wire and tube.



ORDER NO.	PRICE
SIE 182159	\$42.99

**OMC Cobra  
18-22451  
Shift Cable Assembly**  
Replaces: 987661 OMC



ORDER NO.	PRICE
SIE 1822451	\$99.99

**18-2190  
Shift Cable Assembly**  
Replaces: 19543A2  
Mercruiser 1 drives. S/N 6225577 and up.  
For AFT installation into bell housing. For use in applications using core wire with armored strand construction (no support tube)



ORDER NO.	PRICE
SIE 182190	\$59.99

**18-2145 Mercury Bravo  
Shift Cable**  
Replaces: 815471A3



ORDER NO.	PRICE
SIE 182145	\$89.99